

## TEST REPORT

**REPORT NUMBER :** TURT150159086 \_REVISED 01  
**APPLICANT NAME** Hbk Balon Hasan Bülent Kaplangı  
**ADDRESS** Çobançeşme Çalışlar Sok. No:21 Emek İş Hanı Bahçelievler/İstanbul  
Fax No:0212 451 50 85  
**Attention : Hasan bülent kaplangil (bulent@hbkbalon.com)**  
**BUYER** NOT GIVEN  
**SAMPLE DESCRIPTION :** 12 INCH DEKORASYON SERİSİ DIŞ MEKAN  
**Sample 1:** One sample of 12 inch white balloon  
**Sample 2:** One sample of 12 inch mixed balloon  
**Sample 3:** One sample of 12 inch light violet balloon  
**Sample 4:** One sample of 12 inch light blue balloon  
**Sample 5:** One sample of 12 inch pink balloon  
**Sample 6:** One sample of 12 inch violet balloon  
**Sample 7:** One sample of 12 inch blue balloon  
**Sample 8:** One sample of 12 inch orange balloon  
**Sample 9:** One sample of 12 inch ruby balloon  
**Sample 10:** One sample of 12 inch navy balloon  
**Sample 11:** One sample of 12 inch red balloon  
**Sample 12:** One sample of 12 inch bordeaux balloon  
**Sample 13:** One sample of 12 inch yellow balloon  
**Sample 14:** One sample of 12 inch dark turquoise balloon  
**Sample 15:** One sample of 12 inch dark green balloon  
**Sample 16:** One sample of 12 inch light green balloon  
**Sample 17:** One sample of 12 inch black balloon  
**DATE IN :** 07 October, 2015 (13:30)  
**RESUBMIT DATE:** 30 October,2015  
**DATE OUT :** 12 October,2015/ 02 November, 2015  
**COUNTRY OF ORIGIN :** TURKEY

Melihat

Melihat YILDIRIM  
COORDINATOR

Sinan

Sinan ÖNCEL  
Customer Care Manager



**Intertek Test Hizmetleri A.S.**  
Merkez Mahallesi Sanayi Cad. No 23 Altındag Plaza Yenibosna-34197 /İSTANBUL  
Phone : +90 212 496 46 46 Fax: +90 212 452 80 55  
e-mail : intertekcg.turkiye@intertek.com  
<http://www.intertek-turkey.com>



150159086

Test Method	Result	Requirements
-------------	--------	--------------

## ITEM NO:

- Sample 1: 6201
- Sample 2: 6231
- Sample 3: 6203
- Sample 4: 6204
- Sample 5: 6205
- Sample 6: 6206
- Sample 7: 6207
- Sample 8: 6208
- Sample 9: 6209
- Sample 10: 6210
- Sample 11: 6212
- Sample 12: 6214
- Sample 13: 6215
- Sample 14: 6216
- Sample 15: 6218
- Sample 16: 6219
- Sample 17: 6220

## NOTE:

In this revised 01 report, Toxic Element Analysis test results sample 18&19&20&21&22&23&24&25&26&27&28&29&30&31&32&33&34&35&36&37&38&38&40 were removed and Toxic Element Analysis test results sample 1&2&3&4&5&6&7&8&9&10&11&12&13&14&15&16&17 were added by the request of the applicant.

**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /İSTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertekg.turkiye@intertek.com](mailto:intertekg.turkiye@intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result						Requirements
<b>TEST</b>	<b>Sample 1</b>	<b>Sample 2</b>	<b>Sample 3</b>	<b>Sample 4</b>	<b>Sample 5</b>	<b>Sample 6</b>	
SAFETY OF TOYS-PART 1 MECHANICAL AND PHYSICAL PROPERTIES	P	P	P	P	P	P	
SAFETY OF TOYS-PART 2:FLAMMABILITY	P	P	P	P	P	P	
TOXIC ELEMENTS ANALYSIS	P	P	P	P	P	P	
<b>TEST</b>	<b>Sample 7</b>	<b>Sample 8</b>	<b>Sample 9</b>	<b>Sample 10</b>	<b>Sample 11</b>	<b>Sample 12</b>	
SAFETY OF TOYS-PART 1 MECHANICAL AND PHYSICAL PROPERTIES	P	P	P	P	P	P	
SAFETY OF TOYS-PART 2:FLAMMABILITY	P	P	P	P	P	P	
TOXIC ELEMENTS ANALYSIS	P	P	P	P	P	P	
<b>TEST</b>	<b>Sample 13</b>	<b>Sample 14</b>	<b>Sample 15</b>	<b>Sample 16</b>	<b>Sample 17</b>		
SAFETY OF TOYS-PART 1 MECHANICAL AND PHYSICAL PROPERTIES	P	P	P	P	P		
SAFETY OF TOYS-PART 2:FLAMMABILITY	P	P	P	P	P		
TOXIC ELEMENTS ANALYSIS	P	P	P	P	P		

P = MEETS BUYER' S REQUIREMENT / F = DOES NOT MEET BUYER' S REQUIREMENT / NR = NO REQUIREMENT / SC=STILL CONTINUES / X=NOT PERFORMED / NA = NOT APPLICABLE/ LS : LACK OF SAMPLE

The test results relate only to the items tested. The whole and/or the part of this test report shall not be reproduced and shall not be shared with third parties, nor to be used for PR activities without the written permission of INTERTEK Test Hizmetleri A.S.

The reported uncertainty is based on a standard uncertainty multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainty evaluation has been carried out in accordance with ISO/IEC 17025 and TURKAK accreditation requirements. Unless otherwise is specified, all Pass or Fail results are given without uncertainty considered. When uncertainty is taken into account, the result may be borderline. Borderline results need to be re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of TURKAK accreditation. Tests marked (\*) in this test report are not included in the TURKAK accreditation schedule for this laboratory.

"This report (including any enclosures and attachments) are prepared for the exclusive use of the Customer(s) named in the report and solely for the purpose for which it is provided and on the basis of instructions and information and/or materials supplied by Intertek's Customer. The test results relate only to the specific items tested and are not intended to be a recommendation for any particular course of action. Customer is responsible for acting as it sees fit on the basis of such results. Unless Intertek provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Intertek do not accept any liability if this report is used for an alternative purpose from which it is intended, nor do Intertek owe any duty of care to any third party in respect of this report. Except where explicitly agreed in writing, all work and services performed is governed by Intertek Standard Terms and Conditions of Service which is available on request or can be obtained at <http://www.intertek.com/terms>."



Test Method	Result	Requirements
-------------	--------	--------------

*This report details the clauses appropriate to this item. Those clauses not referred to were considered not applicable.*

**Specification: BS EN 71 – 1 : 2014– Safety of Toys – Specification for Mechanical and Physical Properties**

The item was labelled "WARNING ! Children under 8 years can choke or suffocate on uninflated or broken balloons"  
 The item was tested for children aged over 36 months.  
 The item was packaging in a plastic bag which was considered to be disposable.

**Sample 1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17**

SECTION	TEST	RESULTS
4	<b>General Requirements</b>	
4.1	Material	Pass
4.7	Edges	Pass
4.8	Points & Metallic Wires	Pass
4.12	<b>Balloons</b>	Pass
6	<b>Packaging</b>	
a)	Average sheet thickness	Pass
b)	Using drawstring or cords as a means of closing	Pass
7	<b>Warning and Instruction for Use</b>	##
7.2	Toys not intended for children under 36 months	Pass
7.3	Latex Baloons	Pass



Test Method	Result	Requirements
-------------	--------	--------------

## The text of this note is for information only and the indents do not constitute requirements of this European Standard. The information is not exhaustive and Directive 2009/48/EC and the associated guidance documents should be consulted for further details.

The toy or, its packaging or document accompanying must be labelled with:

- The name and address of the manufacturer\*\* **(Present)**
- The name and address of the and importer.\*\* **(Not Present)**
- type, batch, serial or model number or other element allowing of toy identification **(Present)**
- The following advisory note: "Retain for future reference", if the information is not on the toy itself **(Present)**
- A CE mark in the correct shape. **(Present)**
- Warning and other information should be in the national language(s) of the countries where the toy is marketed.

\*\* In the case of the toy sell in European countries, the toy, its packaging or document accompanying must be labelled with the name and address of the manufacturer and importer.



**Intertek Test Hizmetleri A.S.**

*Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /İSTANBUL*

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertekg.turkiye@intertek.com](mailto:intertekg.turkiye@intertek.com)

<http://www.intertek-turkey.com>

---

Test Method	Result	Requirements
-------------	--------	--------------

---

**Specification: BS EN 71 - 2 : 2011+ A1:2014 Safety of Toys – Flammability**

Sample 1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17

SECTION	TEST	RESULTS
4.1	General	
	Celluloid(cellulose nitrate) and materials with a same burning behaviour in fire	Pass

**Intertek Test Hizmetleri A.S.***Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL*

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertekg.turkiye@intertek.com](mailto:intertekg.turkiye@intertek.com)<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 1

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	15.0 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	13.6 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	377.5 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**1-Dark purple**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	5.1 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	4.6 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	131.1 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>



Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**2-Turquoise**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	5.8 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	5.2 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	135.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**3-Orange**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	4.7 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	4.3 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	129.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

*Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL*

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**4-Yellow**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	4.2 ppm	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	4.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	4.0 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	144.4 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

*Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /İSTANBUL*

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

5-Dark pink

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	4.1 ppm	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	4.7 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	3.8 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	140.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 2

6-Red

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	3.9 ppm	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.8 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	4.5 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	147.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements		
<b>Toxic Elements Analysis</b>				
BS EN 71-3:2013+A1:2014				
Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)				
<b>Sample 2</b>				
<b>7-Lilac</b>				
	<b>RESULT (ppm)</b>	<b>DETECTION LIMIT</b>	<b>PASS/FAIL</b>	<b>REQUIREMENT (ppm)</b>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.7 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.2 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	284.6 ppm	<1 ppm	PASS	46000
ppm (Part per million)	=mg / kg			
<	=Less Than			
ND	=Not Detected			
Detection Limit	=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm			



Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**8-Blue**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.9 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.8 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	283.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**9-Baby pink**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.8 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	280.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>



Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

**10-Green**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	9.5 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	6.0 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	106.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

11-White

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	9.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	6.3 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	103.2 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 2**

12-Light green

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	9.9 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	5.8 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	100.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 2

13-Dark green

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	6.5 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	5.7 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	185.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turlkiye.com](mailto:intertek@turlkiye.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 3

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	1.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.1 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	101.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 4**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.5 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	293.3 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 5**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.7 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.2 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	474.9 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 6**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	1.6 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	0.6 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	74.4 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>



Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 7

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.2 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.0 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	423.8 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 8**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	1.0 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	0.9 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	180.2 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 9**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.1 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.0 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	584.2 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 10**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	7.3 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	10.2 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	93.3 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 11

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	9.3 ppm	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	12.5 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	11.6 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	332.2 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 12**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.5 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.1 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	287.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 13**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.9 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	1.3 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	304.7 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 14

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	2.4 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.5 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	337.4 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>



Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 15**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	3.5 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.2 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	341.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

**Sample 16**

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	6.0 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	2.4 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	311.6 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm



**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------

**Toxic Elements Analysis**

BS EN 71-3:2013+A1:2014

Acid extraction method determined by Inductively Coupled Plasma – Mass Spectrometer (ICP / MS)

Sample 17

	<u>RESULT (ppm)</u>	<u>DETECTION LIMIT</u>	<u>PASS/FAIL</u>	<u>REQUIREMENT (ppm)</u>
Antimony (Sb)	Not Detected	<0.1 ppm	PASS	560
Arsenic (As)	Not Detected	<0.1 ppm	PASS	47
Barium (Ba)	Not Detected	<1 ppm	PASS	18750
Cadmium (Cd)	Not Detected	<0.1 ppm	PASS	17
Chromium (III)	Not Detected	<0.1 ppm	PASS	460
Chromium (VI)	Not Detected	0.1 ppm	PASS	0.2
Lead (Pb)	Not Detected	<0.1 ppm	PASS	160
Mercury (Hg)	Not Detected	<0.01 ppm	PASS	94
Selenium (Se)	Not Detected	<0.1 ppm	PASS	460
Aluminium (Al)	7.1 ppm	<1 ppm	PASS	70000
Boron (B)	Not Detected	<1 ppm	PASS	15000
Cobalt (Co)	Not Detected	<1 ppm	PASS	130
Copper (Cu)	Not Detected	<1 ppm	PASS	7700
Manganese (Mn)	Not Detected	<1 ppm	PASS	15000
Nickel (Ni)	Not Detected	<1 ppm	PASS	930
Strontium (Sr)	3.7 ppm	<0.1 ppm	PASS	56000
Tin (Sn)	Not Detected	<1.2 ppm	PASS	180000
Organic tin	Not Detected	<0.1 ppm	PASS	12
Zinc (Zn)	306.9 ppm	<1 ppm	PASS	46000

ppm (Part per million)

=mg / kg

<

=Less Than

ND

=Not Detected

Detection Limit

=Mercury (Hg): <0.01 ppm, Others metal: <0.1 ppm







**Intertek Test Hizmetleri A.S.**

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL





Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)





<http://www.intertek-turkey.com>

Test Method	Result	Requirements
		
		







Test Method	Result	Requirements
		
		



Test Method	Result	Requirements
		
		



Test Method	Result	Requirements
		
		



**Intertek Test Hizmetleri A.S.**

*Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /İSTANBUL*

*Phone : +90 212 496 46 46 Fax: +90 212 452 80 55*

*e-mail : [intertek@turkiye.intertek.com](mailto:intertek@turkiye.intertek.com)*

<http://www.intertek-turkey.com>

Test Method	Result	Requirements
-------------	--------	--------------



## END OF TEST REPORT ##

